ICE MAKER OUTLET BOX

>> 696 SERIES

SPECIFICATION

Sioux Chief 696 series supply OxBox[™] shall be used where necessary in residential or commercial plumbing supply systems. Access box can be secured directly to vertical stud or between studs using galvanized bracket. Supply line can be installed from above or below. Arrester variations can be installed with arrester at any angle. Unit shall be available with ¼-turn valves. Metal support bracket shall install into top/bottom tracks of box. Outlet connection shall be generally ¼". Outlet connections should generally be provided with a test/tamper-resistant cap. Every unit shall include a debris cover for protection during rough-in. Valves will be plated.

MATERIALS

Valve body: no-lead brass¹ Valve shank: no-lead brass¹/copper/PPSU/CPVC, 304SS grip ring Outlet box/frame: ABS Arrester body: stainless steel, C69300 NL brass¹ Arrester piston: GFPP with EPDM o-rings Bracket: galvanized steel

CERTIFICATIONS/APPROVALS

NSF-372 compliant, IAPMO listed box and valve, ASSE 1010 arrester* Valve meets ASME A112.18.1

VALVE/ARRESTER WORKING LIMITS

Max working temperature: 200°F Max air/water testing & working pressure: 150 PSIG

DIMENSIONS

5 ³ /4"
71/4"
33/8"
51/8"
4"
31/2"
51/2"
1/2" nominal
¹ /4" compression
18"

ITEM # SUBMITTED______ JOB NAME______ LOCATION ______ ENGINEER______ CONTRACTOR______ PO#_____ TAG ______



696-G1010XF



696-G1000WR





Create Item Number

696-G10<u>A</u>0<u>BC</u>

e.g. 696-G1010MF: Ice maker supply box with no lead FSWT valve with arrester and frame

ARRESTER A	SUPPLY CONNECTION B	FRAME PACKAGING <u>C</u>	
0 = No arrester	C = ¹ / ₂ " Male CPVC	F = Standard pack	Available Separately: 696-1F: frame only 696-SC1: frame insert w/ hose knockout 696-EX: frame extension
1 = With arrester*	$\mathbf{M} = \frac{1}{2}$ " MIP/F.SWT	(supply box, frame, bracket, debris cover)	
	P = ½" Male sweat/press/push	FPK4 = Display box	
	V = ½" Viega [®] PureFlow [®] PEX	(supply box, frame, bracket, debris cover)	
	W = ¹ ⁄ ₂ " PEX F1960 Grip [™]	FS = Standard pack w/6-ft. braided supply line	
	X = ½" PEX F1807/F2159 Crimp [™]	R = Rough-in pack	
		(supply box, bracket, debris cover)	



OxBox[™]